



### Guidance Notes

Using a vernier (preferably electronic to guarantee finest accuracy):

- take a measurement of the inside diameter of an existing roller from within the machine (or the thickness of the machine shaft) and input this figure to box 1
- Now measure the outside diameter of the existing roller and input this into box 2

It is imperative to ascertain the most accurate measurement down to 00.01 of a millimetre.

